

303 R O.500"

Work Order ID 73835

Friday, September 16, 2011 11:45:28 AM



Page 1

Item ID: D2652

Accept



Setup Start



Revision ID:

Stop



Item Name: Bushing

Start Date: 9/16/2011 Start Qty: 600.00



Cust Item ID:

Required Date: 10/14/2011 Req'd Qty: 600.00



Customer:

Reference:

Run Start



Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D2652

Rev A

100

0.00



Hardinge CNC LATHE SMALL

Hardinge

Memo

0.00

Hardinge CNC Lathe Small

1-TURN AS PER FOLIO FA252 & DWG D2652 FOLIO
REV: N/A DWG REV: A 2-DEBURR AS REQUIRED

579



110

0.00



QC2- Inspect parts off machine FAI/FAIB

QC

Memo

0.00

Quality Control

Handwritten signature and date 11/11/09

579



120

0.00



QC8- Inspect parts - second check

QC

Memo

0.00

Quality Control

Handwritten signature and date 11/11/09

579



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 73835

Page 2

Friday, September 16, 2011 11:45:28 AM

Item ID: D2652

Accept



Setup Start



Revision ID:

Stop



Item Name: Bushing

Start Date: 9/16/2011 Start Qty: 600.00



Cust Item ID:

Required Date: 10/14/2011 Req'd Qty: 600.00



Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start



QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

Identify as per dwg & Stock Location: **ST 19**

0.00



Packaging

Memo

0.00

Packaging

SP 11-11-10.

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

11/11/11**MF 11-11-10**

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, September 16, 2011 11:45:25 AM

Page 1

Work Order ID: 73835



Parent Item: D2652



Parent Item Name: Bushing

Start Date: 9/16/2011

Required Date: 10/14/2011

Start Qty: 600.00

Required Qty: 600.00

Comments: IPP Rev:B 02.06.13 Now machined in house. NG

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

M303R0.500

Purchased

No

100

f

35.9300

0.055

34.73684



303 Round Bar 0.500"



SA WAS

Location

Loc Qty

Loc Code

MAT028

35.93

117143

11.34

118271

11.9

118509

12.69

119009

3.62

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>[Signature]</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE USA, INC. FAIRCHILD INTERNATIONAL AIRPORT, WA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2652	REV. A SHEET 1 OF 1
DATE 97:03:25		TITLE BUSHING	SCALE 1:1

RELEASED
97/04/25 DS



MATERIAL: AISI 303 SS
NOTE: BREAK ALL SHARP CORNERS 0.010 MAX
TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED